

Filter ( ( Cat='Major Issues' OR Cat='Second-Tier Issues' OR Cat='Quality Management Issues') AND Location like '%shanghai%' AND ( status='Pending' OR status='Briefing' OR status='Resolved' OR status='Void'))

Issue No	Date Initiated	Summary	WBS	Location	Initiated By	Proposed Resolution/Status	Construction Response	Design Response	CCO	Cost/Credit	Material	SMR #	Status
Major Issues													
96	16-Oct-08	Initiated by NCR ZPMC-0188  The Contractor has started to blast and paint structural steel without approval of the paint product or approval of the paint facility. The contractor has not submitted to date, the Manufacturing and Fabrication Self Qualification Audit (MFSQA) or requested an audit of the painting facility.		Changxing Island, Shanghai, PRC		METS requests response from Contractor.							Void
125	16-Jun-10	Report is to document RFI revisions regarding Quality Management, Minor Repairs, Material Substitutions, and Shop Drawing Revisions for each Tower Shipment. Brief description of RFIs will be provided under METS Discussion area.		Shanghai, Changxing Island (PRC)		Detailed resolution of RFIs are provided in PMIV. Report is to document these known agreed upon changes by Construction, Design and METS.	Minor Repairs, Shop Drawing Revisions will be shown on the As-builts. Quality Management and Material Substitutions will be noted in "Memo to File" for the project.						Void
Second-Tier Issues													
36	01-Feb-07	Per Cable Team, 1/30/07: 1. Zinc Paste applied on Main Cable Surfaces except under Cable Band, in Saddles, under shrouds, insdie east anchorage; 2. Zinc paste manufacturer on-site for entire application process and will certify completion (approx 3 days).		Cable, Shanghai Pujiang Cable Company, Shanghai, China	ABF-RFI-000532R00	1. Correct; 2. Incorrect--see 10-1.60 of Special Provisions, "Zinc Paste Waterproofing System"--manufacturer representative certifies, Engineer accepts--will accept continuously, no specific time frame. Manufacturer representative need not be present the entire time.							Resolved
63	30-May-07	Special Provisions Section 10-1.61 requires aramid fiber rope tests for elastic modulus and breaking strength. Contractor requests to test the rope with sockets other than Type 1.		Shanghai Pujiang Cable Company, Shanghai, China	ABF-RFI-000727R00	Acceptable, provided assembly realistically tests aramid rope for intended parameters.	Concur with Design.	Test is for ropes, not socket. Type 1 socket not required.					Resolved
66	14-Jun-07	Shanghai Pujiang (SPCC) received an MFSQA audit grade of Contingent Pass for manufacturing parallel wire strand. ABF requests to submit SPCC shop drawings for PPWS cable.		Shanghai Pujiang Cable Company, Shanghai, China	ABF-RFI-000745R00	No objection to shop drawing submittal; ensure contingencies are cleared for Pass before fabrication begins.	Concur.	Concur.					Resolved
Quality Management													
57	22-May-07	Change in anchor bolt location layout proposed.		Changxing Island, Shanghai, PRC		No apparent interference with NDT; no objection.	Concur.	Concur.					Resolved
97	08-Nov-08	This item has been voided.		ZPMC, Changxing Island, Shanghai China									Void
98	16-Nov-08	This item has been voided.		Changxing Island, Shanghai, China									Void